


2026

© Beward R&D Co., Ltd

BEWARD IP Searcher

Software Version History



Version 1.33.0.50713 (17.06.2026)**Integration**

- Integrated multi user intercoms DKS10121_rev7.5.1.12.2 and DKS10121_rev7.5.2.12.2 (firmware 3.7.0.0.1.27.6).
- Integrated access terminal TFR50-205RT (firmware 5.1.2.0.3).
- Integrated SIP monitor SM710W (firmware 3.1.0.0.4.49.2).

Version 1.32.0.50379 (09.04.2026)**Integration**

- Integrated cameras B2220DMR, B22CRW (firmware 3.1.0.0.1.46.32, build date 17.03.2026).
- Integrated cameras B2560RCVZ, B5360DVZ, B5360RCVZ, B5360RVZ2 (firmware 3.1.0.1.1.49.54, build date 30.01.2026).
- Integrated camera SV2012DR (firmware 51.7.0.77-r13).
- Integrated camera SV2018-MR12 (firmware 61.8.0.4-r7).

Version 1.31.0.49806 (03.02.2026)**Integration**

- Integrated camera BFM2530-LP (firmware 3.1.0.2.1.27.36, build date 27.01.2026).
- Integrated camera BFM2530-LPE (firmware 3.1.0.2.1.27.9, build date 27.01.2026).

Version 1.30.0.48474 (25.07.2025)**Integration**

- Integrated video recorder RK2432H (firmware V8.2.4.1-20250521).

Version 1.29.0.46897 (07.10.2024)**Integration**

- Integrated cameras B2530B, B2530RC, B2530RVZ2, B2531RVZ2 (firmware 3.1.0.1.1.27.54, build date 03.06.2024).
- Integrated camera B2560RVZ2 (firmware 3.1.0.0.1.49.13, build date 01.08.2024).
- Integrated camera B5320DMR (firmware 3.1.0.0.1.46.7, build date 26.06.2024).
- Integrated cameras B5350DVZ, B5350RVZ2, B5350RZK, B5350RZQ (firmware 3.1.0.1.1.28.62, build date 31.05.2024).
- Integrated camera B5360B (firmware 3.1.0.1.1.49.6, build date 31.07.2024).
- Integrated cameras B56-20R, B56-30R (firmware 3.1.0.1.1.28.20, build date 08.08.2024).

Version 1.28.0.46523 (09.08.2024)**Integration**

- Integrated multi user intercom DKS20211_rev5.6.6.8.4 (firmware 3.5.0.0.2.26.22, build date 02.02.2024).
- Integrated cameras B89R-5020Z36, B89R-5020Z36F (firmware 43.7.0.74-FD2-r12).
- Integrated camera SV3212DM-PDA (firmware 51.7.0.77-r6).
- Integrated cameras SV4218-R36, SV4218RBZ, SV5018-R36 (firmware 61.8.0.3-r8).

Version 1.27.0.46093 (28.05.2024)

Integration

- Integrated SIP monitors SM730, SM730W (firmware 2.12.44.22.10).

Version 1.26.0.45777 (12.03.2024)

Integration

- Integrated SIP monitor SM700-PS (firmware 3.1.1.0.1.49.30, build date 22.09.2023).
- Integrated SIP monitor SM710 (firmware 3.1.0.0.0.49.5, build date 02.02.2024).
- Integrated camera SV2005DB (firmware 46.7.0.80).
- Integrated camera SV2216RBZ (firmware 33.8.0.3-r3-o7).
- Integrated cameras SV2012DBS, SV2012RCB, SV3212DB, SV3212DBS (firmware 51.7.0.77-r3-c5-t).
- Integrated cameras SV2018-R25, SV2018DVZ, SV2018M, SV2018RBZ2, SV2018RZ, SV2018RZX, SV2218M2, SV3218-R30, SV3218DVZ, SV3218M, SV3218R2, SV3218RZ, SV3218RBZ, SV3218RBZ2, SV3218RZX, SV5018RBZ (firmware 61.8.0.3-r8).
- Integrated camera SV5016RBZ (firmware 31.8.0.3-r3-o7).
- Integrated camera SV6016FLM (firmware 32.8.0.3-r10).

Version 1.25.0.45606 (09.02.2024)

Integration

- Integrated video recorders RK0104, RK0104-P, RK0108, RK0108-P, RK2216, RK2216-P, RK2432, RK3864 (firmware SRV8.2.3.2-20230801).
- Integrated video recorders RK1116, RK1116-P (firmware SRV8.2.3.2-20231214).

Version 1.24.0.45164 (12.12.2023)

System requirements changes

- Starting with this version, the software requires .NET Framework 4.8. This version of .NET Framework is already installed in Windows 10/11 if automatic updates are enabled. The software installer will automatically download and install .NET Framework 4.8 in older versions of Windows, if it is needed (Internet connection is required). If Internet connection is missing on the target computer, please, install .NET Framework 4.8 manually using a standalone installer, which can be downloaded from [Beward](#) or [Microsoft](#) web site.
- Starting with this version, Windows 8 is no longer supported (except Embedded edition). Supported OS versions are: Windows 7 SP1, Windows 8 Embedded, Windows 8.1, Windows 10, Windows 11.

Integration

- Integrated access terminal TFR70-202RB (firmware TFR70-202_3.1.10.0).

New features

- Device web interface can be opened in a browser of the user's choice.
- Settings may be kept during uninstall.

Changes

- Settings and logs moved to AppData\Local\Beward.

Version 1.23.0.44159 (12.07.2023)

Integration

- Integrated camera B2530DMR (firmware 3.1.0.1.1.27.21, build date 12.05.2023).

- Integrated cameras SV2017-MR12, B89R-2217Z36 (firmware 45.7.0.80).
- Integrated cameras SV2217-R36, SV5017-R36 (firmware 45.8.0.3-r3).
- Integrated cameras SV3212RC, SV3212RCB (firmware 51.7.0.77-r2-c2).

Version 1.22.0.43825 (05.05.2023)

Integration

- Integrated cameras B2530DVZ, B2530RVZ, B2530RZK, B2530RZQ (firmware 3.1.0.1.1.27.16).
- Integrated camera B2530RZQ-LP (firmware 3.1.0.1.1.27.6).
- Integrated door station DS07P-LP (firmware 3.1.0.0.2.27, build date 16.01.2023).
- Integrated multi user intercoms DKS15105_rev5.5.6.8.5, DKS15125_rev5.5.6.8.5, DKS15125_rev5.5.6.8.2, DKS15135_rev5.5.6.8.5, DKS15135_rev5.5.6.8.2 (firmware 3.5.0.0.1.27.9, build date 22.11.2022).
- Integrated cameras SV2012DB, SV2012RC (firmware 51.7.0.77).
- Integrated camera SV2012DM-PDA (firmware 51.7.0.77-r2-c2).
- Integrated cameras SV2016DVZ, SV2016M, SV2016RZ, SV2016RZX, SV3216DVZ, SV3216RZ, SV3216RBZ2 (firmware 33.8.0.3-r1).
- Integrated cameras SV3212DM, SV3212DR, SV3212DZ-PDA (firmware 51.7.0.76-r13).
- Integrated SIP monitor SM400W (firmware 2.12.14.5).

Version 1.21.0.43284 (27.12.2022)

Integration

- Integrated camera SV2010DBZ (firmware 40.7.0.80).
- Integrated cameras SV2012DM, SV2012DZ-PDA (firmware 51.7.0.76-r13).
- Integrated cameras SV2016RBZ, SV2016RBZ2, SV3216M, SV3216RBZ, SV3216RZX (firmware 33.8.0.2-r1).
- Integrated camera SV3217RZ2 (firmware 45.7.0.80).
- Integrated access terminal TFR50-202RB (firmware TFR50-202_4.1.8.0).
- Integrated firmware 3.1.0.0.7.18 (build date 22.11.2022) for door station DS06A.

Version 1.20.0.42602 (27.09.2022)

Integration

- Integrated cameras SV2005DR, SV2005RCB (firmware 46.7.0.79-r7).
- Integrated cameras SV2012DZ, SV3212DZ (firmware 51.7.0.76-r10).
- Integrated cameras SV2017-R23, SV2017RZX, SV2218M, SV3217M, SV3217RZX, SV3217-R30, SV3217RBZ, SV5017RBZ (firmware 45.7.0.79-r7).
- Integrated camera SV2017RBZ-LP (firmware 45.7.58.79-LPR_EU-r12).
- Integrated camera SV3210R2 (firmware 40.7.0.79-r7).

Version 1.19.0.42053 (25.07.2022)

Integration

- Integrated multi user intercoms DKS20211_rev5.4.3.8.4, DKS20211_rev5.4.6.8.4 (firmware 3.5.0.0.2.26.5, build date 19.04.2022).
- Integrated multi user intercoms DKS15104_rev5.2.6.8.1, DKS15124_rev5.2.6.8.1, DKS15124_rev5.2.6.8.3, DKS15134_rev5.2.6.8.1, DKS15134_rev5.2.6.8.3 (firmware 3.5.0.0.2.17.4, build date 03.03.2022).
- Integrated firmware 3.1.0.0.7.18 (build date 20.05.2022) for door stations DS06M, DS06A.
- Integrated firmware 3.1.0.0.1.25 (build date 24.05.2022) for door station DS06A.

Version 1.18.0.41482 (29.04.2022)

Integration

- Integrated firmware 3.5.0.0.2.25 (build date 21.01.2022) for multi user intercoms DKS15103_rev5.3.1.0.1, DKS15123_rev5.3.1.0.1, DKS15123_rev5.3.1.0.2, DKS15133_rev5.3.1.0.1, DKS15133_rev5.3.1.0.2.
- Integrated camera BD3595Z33 (firmware bw20220301SX).
- Integrated cameras BD4780DV, BD4780RCV, BD4780RVZ (firmware bw20211220NX).

Version 1.17.0.41110 (23.03.2022)

Integration

- Integrated access terminal TFR70-202 (firmware 3.1.6.0).
- Integrated access terminal TFR80-210T1Q (firmware 1.2.13.0).

Version 1.16.0.40278 (28.10.2021)

Integration

- Integrated cameras SV2005DBS, SV2005DM, SV2005RC (firmware 46.7.58.78-r1).
- Integrated camera SV2017M (firmware 45.7.58.78-r1).

Version 1.15.0.40108 (07.09.2021)

Integration

- Integrated multi user intercom DKS961981_rev5.3.7.0.2 (firmware 3.5.0.0.1.25.3, build date 06.09.2021).

New features

- Added "Firmware version" column into the devices table.
- Added "Copy" item into the devices table context menu to allow copying contents of the table cells to clipboard.

Improvements

- Increased the speed of devices search in the local network.

Version 1.14.0.39800 (30.06.2021)

Integration

- Integrated cameras SV2010DVZ, SV2010RBZ, SV2010RZX, SV3210DB, SV3210RCB (firmware 41.7.58.77-r5).
- Integrated cameras SV2015RZX, SV2215M, SV2215RBZ, SV3215M, SV3215RZ2, SV5020RBZ (firmware 43.7.58.77-r5).

Version 1.13.0.39773 (18.06.2021)

Integration

- Integrated SIP monitor SM700 (firmware 3.1.0.0.1.40.65, build date 24.05.2021).
- Integrated SIP monitor SM700W (firmware 3.1.0.0.1.40.65, build date 24.05.2021).

Version 1.12.0.39648 (25.05.2021)

Integration

- Camera B2520RV (firmware 3.1.0.1.1.25.43) was integrated.

- Camera B2520RVZ (firmware 3.1.0.1.1.25.43) was integrated.
- Camera B2520RZK (firmware 3.1.0.1.1.25.43) was integrated.
- Camera B2520RZQ (firmware 3.1.0.1.1.25.43) was integrated.
- Camera B2520DVZ (firmware 3.1.0.1.1.25.43) was integrated.

Fixes

- Fixed firmware update for TFR series devices.

Version 1.11.0.38738 (24.12.2020)**Integration**

- Device TFR80-210 (firmware 2.1.3.0) was integrated.
- Device TFR80-210-W (firmware 2.1.3.0) was integrated.
- Device TFR70-210 (firmware 3.1.3.0) was integrated.
- Device TFR70-210-W (firmware 3.1.3.0) was integrated.
- Device TFR50-202 (firmware 4.1.3.0) was integrated.

New features

- Added firmware update support for TFR series devices.

Version 1.10.0.38555 (24.11.2020)**Integration**

- Device DKS20210_rev5.4.1 (firmware 3.5.0.0.1.26.6, build date 06.11.2020) was integrated.
- Device TFR80-210T1 (firmware 1.1.8.0.2) was integrated without firmware update support.

Version 1.9.0.38317 (08.10.2020)**Integration**

- Camera SV3215-R30P2 (firmware 43.7.58.75-r4) was integrated.

Version 1.8.0.38248 (28.09.2020)**Integration**

- Camera SV5020-R36 (firmware 43.7.58.75-r4) was integrated.

Version 1.7.4.38026 (25.08.2020)**Integration**

- Device DKS15103_rev5.3.1.0.1 (firmware 3.5.0.0.1.25, build date 05.08.2020) was integrated.
- Device DKS15123_rev5.3.1.0.1 (firmware 3.5.0.0.1.25, build date 05.08.2020) was integrated.
- Device DKS15123_rev5.3.1.0.2 (firmware 3.5.0.0.1.25, build date 05.08.2020) was integrated.
- Device DKS15133_rev5.3.1.0.1 (firmware 3.5.0.0.1.25, build date 05.08.2020) was integrated.
- Device DKS15133_rev5.3.1.0.2 (firmware 3.5.0.0.1.25, build date 05.08.2020) was integrated.
- Camera B2230-LP (firmware 3.1.0.0.2.19.105) was integrated.

Version 1.7.3.37733 (08.07.2020)**Integration**

- Camera SV2015-R23P2 (firmware 43.7.58.74-r1) was integrated.
- Camera SV2215-R36P2 (firmware 43.7.58.74-r1) was integrated.
- Camera B4230RVZ (firmware 3.1.0.0.2.19.113, build date 11.06.2020) was integrated.
- Camera B4230RCVZ (firmware 3.1.0.0.2.19.113, build date 11.06.2020) was integrated.

- Device DSN06PS (firmware 3.1.15.0.6.18.22) was integrated.

Version 1.7.2.36767 (21.01.2020)

Integration

- Device DKS1510x_rev2.2 (firmware 3.2.0.0.3.17.94) was integrated.
- Device DKS1510x_rev2.2.1 (firmware 3.2.0.0.3.17.94) was integrated.
- Device DKS1510x_rev3.2.1 (firmware 3.3.0.0.3.17.20) was integrated.
- Device DKS1512x_rev2.2 (firmware 3.2.0.0.3.17.94) was integrated.
- Device DKS1512x_rev2.2.1 (firmware 3.2.0.0.3.17.94) was integrated.
- Device DKS1512x_rev3.2.1 (firmware 3.3.0.0.3.17.20) was integrated.
- Device DKS85010x_rev2.2.1 (firmware 3.2.1.4.3.17.51) was integrated.
- Device DKS85012x_rev2.2.1 (firmware 3.2.1.4.3.17.51) was integrated.
- Device DP303M (firmware 3.1.8.1.6.18.1, build date 07.11.2019) was integrated.
- Firmware 3.1.0.0.5.17 (build date 11.12.2019) was integrated for IP portal DK103M.

Version 1.7.1.36484 (15.11.2019)

Integration

- Firmware 3.1.0.0.1.25.28 was integrated for door station DS06A(P).

Version 1.7.0.36433 (06.11.2019)

Integration

- Camera B57-30RW (firmware 3.1.0.1.2.19.90) was integrated.
- Camera SV2010DM (firmware 41.7.58.72-r2) was integrated.
- Camera SV3210RZ2 (firmware 41.7.58.72-r2) was integrated.
- Firmware 41.7.58.72-r2 was integrated for cameras SV3210xx, SV2015M, SV2215B.
- Firmware 43.7.58.72-r2 was integrated for cameras SV3215xx, SV6020FLM.

Version 1.6.18.36062 (22.08.2019)

Integration

- Device DKS15374 (firmware 3.1.0.0.3.17.12) was integrated.

Version 1.6.17.35774 (22.07.2019)

Integration

- Camera B89R-3595Z33 (firmware bw20190618RSp) was integrated.
- Camera SV3215-R30P (firmware 43.7.58.71-r4) was integrated.
- Firmware bw20190604NSP was integrated for cameras BD4680xxx.
- Firmware bw20190604NSQ was integrated for cameras BD4640xxx.
- Firmware bw20190409NSZ was integrated for cameras BD3670xxx, BD3990xxx, BD3590xxx, BD134P, BD136P, BD137P.
- Firmware bw20190618RP was integrated for cameras BD4685xxx.
- Firmware bw20190618RS was integrated for cameras BD3595Z33, BD142P30, BD143P30.

Version 1.6.16.35298 (16.04.2019)

Integration

- Camera BD208R22 (firmware bw20190211T2) was integrated.

- Camera SV2015M (firmware 41.7.58.69) was integrated.
- Camera SV2215B (firmware 41.7.58.69) was integrated.
- Camera SV3210M (firmware 41.7.58.69) was integrated.
- Camera SV3215RBZ (firmware 43.7.58.69) was integrated.
- Firmware 41.7.58.69 was integrated for cameras SV3210xx.
- Firmware 43.7.58.69 was integrated for cameras SV3215xx, SV6020FLM.
- Firmware 3.1.0.0.3.17 (build date 28.12.2018) was integrated for cameras B2710xx.
- Firmware 3.1.0.1.2.19.86 (build date 25.01.2019) was integrated for camera B55-5H.
- Firmware bw20190212NSXp was integrated for camera B89R-5260Z18.

Version 1.6.15.34829 (08.02.2019)

Integration

- Camera BD142P30 (firmware 41.7.58.69) was integrated.
- Camera BD143P30 (firmware 41.7.58.69) was integrated.
- Camera SV3210DBS (firmware 41.7.58.69) was integrated.
- Camera SV3210DBZ (firmware 41.7.58.69) was integrated.
- Camera SV3215DVZ (firmware 43.7.58.69) was integrated.
- Camera SV3215RZ (firmware 43.7.58.69) was integrated.
- Camera SV3215RZX (firmware 43.7.58.69) was integrated.
- Firmware bw20181207RP was integrated for cameras BD4685, BD4685DVZ, BD4685RVZ.
- Firmware bw20190116NSZ was integrated for cameras BD3670xxx, BD3990xxx, BD3590xxx, BD134P, BD136P, BD137P.

Version 1.6.14.34387 (30.11.2018)

Integration

- Camera BD4685DV (firmware bw20181009RP) was integrated.
- Camera BD4685RV (firmware bw20181009RP) was integrated.
- Camera BD4685RVZ (firmware bw20181009RP) was integrated.
- Camera SV3210DR (firmware 41.7.58.67-r18) was integrated.
- Door station DS06A(P) (firmware 3.1.0.0.6.18, build date 09.11.2018) was integrated.

Version 1.6.13.34188 (12.11.2018)

Integration

- Camera SV3210D (firmware 41.7.58.67-r18) was integrated.
- Camera SV3210DM (firmware 41.7.58.67-r18) was integrated.
- Camera SV3210DVZ (firmware 41.7.58.67-r18) was integrated.
- Camera SV3210R (firmware 41.7.58.67-r18) was integrated.
- Camera SV3210RC (firmware 41.7.58.67-r18) was integrated.
- Camera SV3210RZ (firmware 41.7.58.67-r18) was integrated.
- Camera SV3210RZX (firmware 41.7.58.67-r18) was integrated.
- Camera SV3210-R30 (firmware 41.7.58.67-r18) was integrated.
- Camera SV6020FLM (firmware 43.7.58.67-r1) was integrated.
- Firmware 41.7.58.67-r18 was integrated for camera SV3210RBZ.

Version 1.6.12.33997 (23.10.2018)

Integration

- Camera SV3210RBZ (firmware 41.7.58.66) was integrated.

Version 1.6.11.33832 (26.09.2018)

Integration

- Camera BD3595Z33 (firmware bw20180625RS) was integrated.
- Firmware 3.1.0.0.4.18.4 was integrated for IP encoder B102S.

Version 1.6.10.33595 (21.08.2018)

Integration

- Camera B2230 (firmware 3.1.0.0.2.19.73) was integrated.
- Camera B2230RVZ (firmware 3.1.0.0.2.19.73) was integrated.

Version 1.6.9.33337 (13.07.2018)

Integration

- Device DKS15100 (firmware 3.1.0.0.3.18.4) was integrated.
- Device DKS15120 (firmware 3.1.0.0.3.18.17) was integrated.
- Device DKS15121 (firmware 3.1.0.0.3.18.58) was integrated.
- Firmware bw20180515NSP was integrated for camera BD4680DRZ.
- Firmware bw20180515NSQ was integrated for cameras BD46C, BD4640RCV2.
- Firmware bw20180515NSZ was integrated for cameras BD3670M, BD3990FL2, BD136P.
- Firmware bw20180517NSX was integrated for camera BD3730M.

Version 1.6.8.32847 (03.05.2018)

System requirements changes

- Starting with this version, the software requires .NET Framework 4.6.1. Full version of the installer is required to upgrade the software.
- Starting with this version, Windows XP and Vista are no longer supported. The minimal supported OS version is Windows 7 SP1.

Integration

- Camera B89L2-5230Z40 (firmware 3.1.0.0.2.19.76) was integrated.
- Camera BD4685 (firmware bw20180412RP) was integrated.
- Camera BD4685DVZ (firmware bw20180412RP) was integrated.
- Camera B2230L (firmware 3.1.0.0.2.19.74) was integrated.
- Firmware 3.1.0.0.6.18 was integrated for door stations DS03M(P), DS05M(P), DS06, DS06M.
- Firmware 3.1.0.0.4.18 was integrated for IP portal DK103 / Wi-Fi.
- Firmware 3.1.0.0.4.18 was integrated for IP portal DK103M / Wi-Fi.

Version 1.6.7.32347 (19.02.2018)

Integration

- Camera B1731C (firmware 3.1.1.1.5.18.1) was integrated.
- Camera B1731CW (firmware 3.1.1.1.5.18.1) was integrated.
- Camera B1731CR (firmware 3.1.1.1.5.18.1) was integrated.
- Camera B1731CRW (firmware 3.1.1.1.5.18.1) was integrated.
- Camera B1731DM (firmware 3.1.1.1.5.18.1) was integrated.
- Camera B236518RV (firmware 3.1.1.1.3.17.1) was integrated.
- Camera B28325DV (firmware 3.1.1.1.3.17.1) was integrated.
- Camera B28325R2 (firmware 3.1.1.1.3.17.1) was integrated.
- Camera B23510Z20 (firmware 3.1.1.1.2.19.1) was integrated.
- Door station model DSN23215P (firmware 3.1.1.2.6.18.1) was integrated.

- Door station model DSN23215PS (firmware 3.1.1.3.6.18.1) was integrated.
- Camera B236518RVZ (firmware 3.1.1.1.3.17.2) was integrated.

Version 1.6.6.32191 (23.01.2018)

Integration

- Camera CD630-4G (firmware CD1.0.0.0.3.18) was integrated.
- Camera CD310 (firmware CD1.0.0.0.3.18) was integrated.
- Camera CD330 (firmware CD1.0.0.0.3.18) was integrated.
- Firmware CD1.0.0.0.3.18 was integrated for cameras CD300, CD320, CD400, CD630.

Version 1.6.5.32181 (12.01.2018)

Integration

- Camera B12CR (firmware 3.1.0.1.5.18) was integrated.
- Camera B12CRW (firmware 3.1.0.1.5.18) was integrated.
- Camera B85-20H2 (firmware 3.1.0.1.2.19) was integrated.

Version 1.6.4.31892 (16.11.2017)

Integration

- Camera B4230 (firmware 3.1.0.0.2.19.56) was integrated.

Version 1.6.3.31803 (02.11.2017)

Integration

- IP encoder B102S(W/4G) (firmware 3.1.0.0.3.18) was integrated.

Version 1.6.2.31454 (23.08.2017)

Integration

- Camera B55-5H (firmware 3.1.0.1.2.19.51) was integrated.

Version 1.6.1.31369 (04.08.2017)

Integration

- Camera B2710DV (firmware 3.1.0.0.3.17.46) was integrated.
- Camera B2710DVZ (firmware 3.1.0.0.3.17.46) was integrated.
- Camera B1510DV (firmware 3.1.0.1.5.18.68) was integrated.

Version 1.6.0.31111 (22.06.2017)

Integration

- Camera B1510RCVZ (firmware 3.1.0.1.5.18) was integrated.
- Camera B2710RCVZ (firmware 3.1.0.0.3.17) was integrated.
- Camera B1510 (firmware 3.1.0.1.5.18) was integrated.
- Camera B1510-4G (firmware 3.1.0.1.5.18) was integrated.
- Camera B2710-4G (firmware 3.1.0.0.3.17) was integrated.
- Camera B1510DMR (firmware 3.1.0.1.5.18) was integrated.
- Firmware bw20170419NSX was integrated for BD series cameras.
- Firmware bw20170419NSXp was integrated for B89R-5260Z18.

- Firmware 3.1.0.0.3.17.29 was integrated for B2710.

New features

- Search for devices connected to the computer via vpn channels using OpenVPN was implemented.

Version 1.5.6.30730 (12.04.2017)**Integration**

- IP portal DK103M with Wi-Fi and 4G support was integrated (firmware 3.1.0.0.3.18).
- Camera B12CW (firmware 3.1.0.1.5.18.36) was integrated.
- Firmware 3.1.0.0.3.18 was integrated for DK103.

Version 1.5.5.30630 (30.03.2017)**Integration**

- Door station model AD103IPP (firmware 3.1.10.0.5.18) was integrated.
- IP portal AD209IPC (firmware 3.1.10.0.3.18) was integrated.
- Firmware 3.1.0.0.5.18 was integrated for DS03M(P), DS05M(P), DS06, DS06M.

Version 1.5.4.30457 (21.02.2017)**Integration**

- Camera B55-3H (firmware 3.1.0.0.2.19.14) was integrated.

Version 1.5.3.30348 (08.02.2017)**Integration**

- BK series NVRs (firmware 4.1.1.0) were integrated.
- Camera BD4640DM (firmware bw20170116NSQ) was integrated.
- Camera BD3670FL2 (firmware bw20161124NSZ) was integrated.
- Firmware bw20161213NSP was integrated for BD4680DRZ.
- Firmware bw20170116NSQ was integrated for BD46C, BD4640RCV2.
- Firmware 3.1.0.1.5.18.24 was integrated for B1510DR.
- Camera B96-30H (firmware 3.1.0.0.2.19.12) was integrated.

Version 1.5.2.29843 (12.12.2016)**Integration**

- Camera B85-20H (firmware 3.1.0.0.2.19.4) was integrated.

Version 1.5.1.29708 (25.11.2016)**Integration**

- Camera BD134P (firmware bw20161124NSZ) was integrated.
- Camera BD136P (firmware bw20161124NSZ) was integrated.
- Door station model DS06M(P) (firmware 3.1.0.0.5.18.5) was integrated.
- Firmware 3.1.0.0.4.18 was integrated for DS03M(P), DS05M(P), DS06.
- Camera BD3990FLM (firmware bw20161012NSZ) was integrated.

Version 1.5.0.29408 (20.10.2016)

Integration

- Camera B89R-5260Z18 (firmware bw20160929NSXp) was integrated.
- Camera BD5260 (firmware bw20160726NSX) was integrated.
- Camera BD5260Z18 (firmware bw20160726NSX) was integrated.
- Firmware 3.1.0.0.2.18 was integrated for IP portal DK103W.

New features

- Devices with multiple network interfaces are displayed in the list in one line, containing the list of interfaces.

Version 1.4.11.29182 (21.09.2016)

Integration

- Camera B1510RV (firmware 3.1.0.1.5.18.7) was integrated.
- Camera B1510DR (firmware 3.1.0.1.5.18.7) was integrated.
- Camera BD3990FL2 (firmware bw20160825NSZ) was integrated.
- Firmware 3.1.0.0.1.19 was integrated for cameras B5650, B2250.
- Door station model DS06 (firmware 3.1.0.0.4.18.54) was integrated.

Version 1.4.10.28957 (22.08.2016)

Integration

- Camera B1710DMR (firmware 3.1.0.1.4.18) was integrated.
- Firmware bw20160728NSQ was integrated for cameras BD46C, ...
- Firmware bw20160728NSZ was integrated for cameras BD3670FL, BD137P, ...
- Firmware bw20160728NSA was integrated for cameras BD3570RVZ, BD135P, ...
- Firmware bw20160728NSP was integrated for cameras BD4680RVZ, ...
- Firmware 3.1.0.1.4.18 was integrated for cameras B1210R, B1210DM, B12C, B1710, B1710DM, B1710DR, B1710RV, B54-2-IP2, B85-2-IP2.

Version 1.4.9.28740 (29.07.2016)

Integration

- Camera BD4640DS (firmware bw20160727NSQ) was integrated.
- Door station model DS06M(P) (firmware 3.1.0.0.4.18.31) was integrated.

Changes

- The regulations of entering the firmware update mode were changed: when the firmware update window is opened the automatic device connection attempt is not made; the password, login fields and the Check button are enabled. Device connection attempts are made only after the user clicks the Check button.

Version 1.4.8.28653 (18.07.2016)

Integration

- Camera B96-30 (firmware 3.1.0.0.3.16) was integrated.
- Camera (firmware 3.0.0.0.1.18) was integrated.
- Firmware bw20160629NSQ was integrated for cameras BD46C, ...
- Firmware bw20160620NSZ was integrated for cameras BD3670FL, BD137P, ...
- Firmware bw20160621NSA was integrated for cameras BD3570RVZ, BD135P, ...
- Firmware bw20160412NSX was integrated for cameras BD3270RVZX, BD3270Z18, ...

Version 1.4.7.28465 (21.06.2016)

Integration

- Camera B2710DMR (firmware 3.1.0.0.2.17) was integrated.
- Firmware 3.1.0.0.2.16 was integrated for cameras B2720RZK, B2720RZQ.
- Firmware 3.1.0.0.2.17 was integrated for cameras B2710, B2710R, B2710DM, B2710DR, B2710RV, B2710RVZ.

Version 1.4.6.28235 (20.05.2016)

Integration

- Camera B2710 (firmware 3.1.0.0.1.17) was integrated.
- Firmware bw20160317NSA was integrated for cameras BD3570DRZ, BD35C, BD135P, ...
- Firmware bw20160330NSQ was integrated for cameras BD46C, BD4640RCV2, ...
- Firmware bw20160329NSP was integrated for cameras BD4680DRZ, ...
- Firmware 3.1.0.1.3.18 was integrated for cameras B1210xx, B1710xx.
- Firmware 3.1.0.0.2.21 was integrated for video servers B1018, B1114.

Version 1.4.5.27955 (05.04.2016)

Integration

- Camera B2710RVZ (firmware 3.1.0.0.2.17.1) was integrated.
- Video server B1114 (firmware 3.1.0.0.1.21) was integrated.
- Camera BD4680RV (firmware bw20160205NSP) was integrated.
- Camera CD300 (firmware CD1.0.0.0.0.18) was integrated.
- Camera CD320 (firmware CD1.0.0.0.0.18) was integrated.
- Camera CD400 (firmware CD1.0.0.0.0.18) was integrated.
- Camera CD630 (firmware CD1.0.0.0.0.18) was integrated.
- Firmware 2.1.0.2.53.15 was integrated for cameras B55-3, B85-20.

Version 1.4.4

Integration

- IP portal DK103 (firmware 3.1.0.0.1.18.16) was integrated.
- IP encoder B101S (firmware 3.1.0.0.1.18.11) was integrated.
- Camera BD4640DR (firmware bw20160205NSQ) was integrated.
- Firmware 3.1.0.0.2.16 was integrated for cameras B2720RV, B2720DV, B2720RVZ, B2720DVZ, B2720.
- Firmware 3.1.0.0.3.18 was integrated for door stations DS05M(P), DS03M(P).

Version 1.4.3

Integration

- Camera B5650 (firmware 2.1.0.2.52.19) was integrated.
- Camera BD4640RC (firmware bw20151102NSQ) was integrated.
- Camera BD4640RCV (firmware bw20151102NSQ) was integrated.
- Camera BD4640RCV2 (firmware bw20151102NSQ) was integrated.
- Door station model DS05M was integrated (firmware 3.1.0.0.2.18).

Version 1.4.2

Integration

- Video recorders BDR16V(P) (firmware 201511160) were integrated.
- Camera BD4680DRZ (firmware bw20151203NSP) was integrated.
- Camera BD46C (firmware bw20150915NSQ) was integrated.
- Camera BD4680 (firmware bw20151203NSP) was integrated.
- Camera BD4680DRV (firmware bw20151203NSP) was integrated.
- Camera BD4680RVZ (firmware bw20151203NSP) was integrated.
- Firmware 3.1.0.0.1.17 was integrated for cameras B2710R, B2710RV, B2710DM, B2710DR.

Version 1.4.1

Integration

- Camera B54-2-IP2 (firmware 2.1.0.2.52.18) was integrated.
- Camera B85-x-IP2 (firmware 2.1.0.2.52.18) was integrated.

Version 1.4.0

Integration

- Camera B2720RZK (firmware 3.1.0.0.1.16) was integrated.
- Camera B2720RZQ (firmware 3.1.0.0.1.16) was integrated.
- Camera CD1210DM (firmware CD1.0.0.0.0.18.27) was integrated.
- Camera CD1210R (firmware CD1.0.0.0.0.18.27) was integrated.
- Camera BD3270Z18 (firmware bw20150715NSX) was integrated.
- Camera BD3270RVZX (firmware bw20150715NSX) was integrated.
- Camera BD3570RCV2 (firmware bw20150707NSA) was integrated.
- Camera BD3730M (firmware bw20150715NSX) was integrated.
- Firmware 3.1.0.0.1.16 was integrated for cameras B2720RV, B2720DV, B2720RVZ, B2720DVZ, B2720.
- Firmware bw20150806NSZ was integrated for cameras BD3670FL, BD137P.

New features

- The following operations were added: device firmware upgrade, device reboot, device parameters reset to default values.

Version 1.3.0

New features

- An ability to switch the interface language was added: Russian, English.

Version 1.2.0

Integration

- Digital video recorder BS1112 (firmware V3.0.2.3-K/V1.1.5.8/V0.0.0.0-1U-III) was integrated.
- Digital video recorder BS1232 (firmware V3.0.2.3-H/V1.1.6.0/V1.0.0.2-1U-IV) was integrated.
- Camera B2710RV (firmware 2.1.0.2.50.17) was integrated.
- Camera BD4630RC (firmware bw20150615NSA) was integrated.
- Camera BD4630RCV2 (firmware bw20150615NSA) was integrated.
- Camera BD4690RV (firmware bw20150528NSZ) was integrated.
- Camera BD4690RVZ (firmware bw20150528NSZ) was integrated.
- Camera BD3590Z30 (firmware bw20150601NSZ) was integrated.
- Firmware 2.1.0.2.51.18 was integrated for cameras B1210xx, B1710xx.

Version 1.1.8

Integration

- Camera B85-20 (firmware 2.1.0.1.58.15) was integrated.
- Camera B89R-3270Z18 (firmware bw20150408NSXp) was integrated.
- Firmware bw20150306NSA was integrated for cameras BD43C, BD3570RVZ, BD2570RVZ, BD135P.

Version 1.1.7

Integration

- Camera N520 (firmware M2.1.6.05C033) was integrated.
- Camera B2250 (firmware 2.1.0.1.56.19) was integrated.

Version 1.1.6

Integration

- Camera B1210DM (firmware 2.1.0.1.56.18) was integrated.
- Camera BD137P (firmware bw20141224NSZ) was integrated.
- Firmware bw20141229NSA was integrated for cameras BD3570DV, BD4330RVZX, BD4330RV, BD3570, BD2570, BD133, BD135, BD75-5P, BD3570D, BD3570DM, BD3570DR, BD3570DRZ, BD3570RC, BD3570RCV, BD3570RVZX, BD3570RVZ, BD3570RV, BD4330D, BD4330R, BD4330RH, BD4330RVZH, BD4370D, BD4370RV, BD4570, BD2570DVZ, BD4330RVH, BD4330RVZH, BD4330DH, BD4330DM, BD4330DS, BD4330H, BD43C, BD35C.

Version 1.1.5

Integration

- Camera B2720DVZ (firmware 2.1.0.1.54.16) was integrated.

Version 1.1.4

Integration

- Camera B2720RVZ (firmware 2.1.0.1.54.16) was integrated.
- Firmware 2.1.0.1.52.15 was integrated for camera B55-3.
- Firmware w20130117ANS was integrated for camera BD4070.
- Firmware 2.1.0.1.55.18 was integrated for camera DS03M(P).

Version 1.1.3

Integration

- Camera B2720DV (firmware 2.1.0.1.54.16) was integrated.
- Firmware bw20140902NSZ was integrated for camera BD3670M.
- Firmware bw20140902NSZ was integrated for camera BD3670FL.
- Firmware bw20140910NSA was integrated for camera BD35C.
- Firmware bw20140910NSA was integrated for camera BD43C.
- Firmware 2.1.0.1.54.16 was integrated for camera B2720.
- Firmware 2.1.0.1.54.16 was integrated for camera B2720RV.

Version 1.1.2

Integration

- Camera B2710R (firmware 2.1.0.1.53.17, web 2.1.2.9 (20140526)) was integrated.

Version 1.1.1

Integration

- Cameras B2710DM, B2720RV were integrated.